## Longitudinal Process Flowchart 20" - 56" /508 - 1422 mm/

1. Infeed of plates Identity check



5. Tack welding



9. UT of weld



13. Hydrostatic testing



17. Inspection, weighing, marking, stamping



2. Milling of longitudinal plate edges



6. Inside welding



10. X-ray testing of weld seam



14. UT of weld seam



18. Storage



3. Forming by the 3-roll bending process



7. Outside welding



11. Mechanical expanding



15. X-ray testing of weld seam and pipe ends



4. Post-bending of the longitudinal plate edges



8. Visual control



12. Grinding of weld at pipe ends and beveling



16. Magnetic particle and ultrasonic inspection of both pipe ends

